






CP2020H



CP2020H




A x20
Spec: $\varnothing 8 \times 30$



B x12
Spec: $\varnothing 7 \times L30$




C x12
Spec: $\varnothing 15 \times H12$



D x16
Spec: $\varnothing 6 \times L28$



E x16
Spec: $\varnothing 12 \times H9$




F x8
Spec: $\varnothing 3.5 \times L35$




G x8
Spec: $\varnothing 6 \times 30$



H x12
Spec: $\varnothing 6 \times L8$



I x2
Spec: L350



J x8
Spec: $\varnothing 7 \times L48$



K x8
Spec: $\varnothing 15 \times H15$




L x8
Spec:



M x1
Spec: 10g



N x28
Spec:




O x8
Spec: $\varnothing 3.8 \times L32$



P x6
Spec: $\varnothing 10 \times H1$





AAA x8
Spec: $\varnothing 3.8 \times L12$



1


2






3


4






5


6




7




8






9

10





11
