






CP2204TV1-HA



CP2204TV1-500



A x20
Spec: $\varnothing 8 \times 30$



B x24
Spec: $\varnothing 7 \times L30$



C x24
Spec: $\varnothing 15 \times H12$



D x12
Spec: $\varnothing 6 \times L28$




E x12
Spec: $\varnothing 12 \times H9$



F x12
Spec: $\varnothing 6 \times L8$



G x10
Spec: M6*50




H x8
Spec: $\varnothing 3.5 \times L35$





I x24
Spec: $\varnothing 6 \times 30$



J x2
Spec: 10g



K x2
Spec: L400



L x8
Spec: $\varnothing 3.8 \times L32$



M x36
Spec:



N x4
Spec: M6*35



O x1
Spec: 5#




P x14
Spec: 5/16*L25




Q x28
Spec: $\varnothing 8.2 \times \varnothing 14$



AAA x8
Spec: $\varnothing 3.8 \times L12$




1




2


3




4




5




6




7




8






9

10





11

12

