




LC-0107A




Assembly list




x 1




x 1




x 1



x 4



x 1



x 1



Ax9



Bx8



Cx8




Dx3




Ex2



Fx2





x1



x1

Assembly


1




OK

Assembly

2




OK




A:8 x

Assembly

3




OK



M6*14

Dx3




5#

x1

Assembly


4



Fx2





Ex2




x1

Assembly

5



OK




or



Bx8



Cx8



x1



Ax1