






CP1506H2



CP1506H2



A x20
Spec: $\varnothing 8 \times 30$



B x16
Spec: $\varnothing 7 \times L30$




C x16
Spec: $\varnothing 15 \times H12$



D x2
Spec: $\varnothing 6 \times 30$



E x4
Spec: $\varnothing 3.5 \times L16$



F x4
Spec: H13



G x1
Spec: 10g



H x10
Spec:



I x2
Spec: $\varnothing 6 \times L28$




J x2
Spec: $\varnothing 12 \times H9$



K x4
Spec: $\varnothing 3.5 \times L35$




L x10
Spec: $\varnothing 3.5 \times L11$



M x1
Spec: L300




N x12
Spec:



O x4
Spec: $\varnothing 7 \times L48$





P x4
Spec: $\varnothing 15 \times H15$



1


2






3


4







5

6







8




9



10





12

