




Assembly Instruction

Model: W-401

NO	DESCRIPTION	SKETCH	SIZE	QTY
A	Screw		M8x90	6
B	Crescent piece			6
C	Nut		M8	6
D	Wood dowel			8
E	Spanner			1
F	Leg			2
G	Middle board			1
H	Table top			1

